Final Report - Drilling Operations Conoco-Pelican-Gulf 7/9-1 1038

#### General

Conoco-Pelican-Gulf well 7/9-1 was drilled in the Norwegian North Sea in April and May 1971. The well was spudded on 22nd April and required 35 days to complete. T.D. was 9614'. The Zapata jackup, "Maersk Explorer", was used on this well. Water depth was 224' and conventional surface control equipment was used. In general the operations were trouble-free and the well was plugged and permanently abandonned as a dry hole.

Bits

Seventeen bits were used as follows:

No.	Size	Footage	Hours	Ft./Hrs.
1 `	26"	1172	36	32.6
1	17-1/2"	2029	. 35	58.2
4	12-1/4"	- 3527	751	46.8
10	8-1/?"	2235	·** 102 <sup>°</sup>	21.9
1	8-7/15"	284	34 <del>1</del>	8,25
1.	8-15/32"	core head 37	$6\frac{1}{2}$	5.7

All bits were jet type except the 26", and all except the 26" and  $17\frac{1}{2}$ " were sealed searing. In the upper part of the hole some of the bits were pulled prematurely. A copy of the bit record is attached.

#### Coring

Two cores were attempted using a Christensen conventional core barrel and a Christensen C-22 core head.

The first core, 7249 - 7273, recovered 15½ feet. The core barrel had jammed. Formation was a chalky limestone of Danian ege. The second core, 7403 - 7416, recovered 10 feet. The barrel had jammed again. Formation was a chalky limestone of Maestrichtian age. The cores were cut using 10 - 12,000 lbs weight and 130 - 160 R.P.M: Pump pressure was 1400 - 1500 and circulation rate 260 G.P.M:

## Casing and Cementing.

30" conductor pipe was driven to refusal at 355' RKB - 25' penetration using a D-44 Hammer. By using a high viscosity gel mud and careful drilling, circulation was maintained and the hole was drilled to the 20" casing point: 1502'.

The 20" 8 round casing stuck; after running 20 joints, at 793'. The pipe was cemented with 800 sacks class B + 12% gel cement, tailed in with 300 sacks neat class B. Coment was returned to the surface.



Cont...2..

Final Report - Drilling Operation C-P-G- 7/9-1 cont ..

The 13-3/8" casing was run at 3511' after a  $17\frac{1}{2}"$  hole had been drilled to 3531'. 92 joints of K-55 buttress were used. The pipe was cemented with 1800 sacks of class B + 12% gel followed by 300 sacks class B neat. A Cameron mud line hanger run at 341', was backed off to wash the cement out of the annulus. Considerable difficulty was experienced in the attempt to reconnect this riser, finally requiring the removal of the lower threads on the pin end of the hanger.

172 joints 47 lbs 9-5/8" N-80 buttress casing, a total of 7034', was run and landed in the mud line hanger at 341'. The pipe was cemented with 1700 sacks class B + 4% gel tailed in with 800 sacks neat class B, retarded.

Some cement returns were observed. The annulus was washed out and the mud line hanger reconnected and tested without incident.

#### Mud

Total mud cost on this well was approximately \$ 70,000. The well was spudded using a high viscosity gel-seawater mud. After a if drilling out of the 20" casing, which stuck at 793', the mud was converted to a ligno sulfonate-seawater. The 700' of 26" rathole left below the 20" casing gave considerable trouble by acting as a build up area for large balls of gumbo which collected there as  $17\frac{1}{2}$ " hole was being made. Annular velocity in this part of the hole, even with a circulation rate of 900 G.P.M. was probably less than 30 f.p.m. An attempt to run electric logs at the i3-3/8" casing point failed because of the fill at 1450'.

Drilling detergent was used to reduce torque and drag and was successful in the upper part of the hole. Toward T.D. an increase in mud weight to 14.0 ppb was necessary to further reduce excessive torque.

Mud supplier was Magcobar. A copy of the mud summary is attached.

#### Comments

The total rig days charged to the well include 5 days waiting on weather at the end of the operation.

A deviation problem argse in the  $8\frac{1}{2}$ " hole, starting around 7400' where the angle was  $4\frac{1}{2}$ . It increased steadily and at 8933' the last survey point was  $5\frac{1}{2}$ . Light bit weight, high rotary speeds, and a bottom hole assembly usually successful in dropping angle had no effect.

# CONOCO NORWAY, INC

P.O.Box 130 4056 Tananger, Norway.

#### 3rd May 1971.

## SUMMARY OF DRILLING OPERATIONS

CONOCO-PELICAN-GULF 7/9/1

1530 Hours April 20th - 0800 Hours May 3rd, 1971 Reports as of 0800 am for day reported covering previous 24 hours.

APRIL 21, 1971

161 Hrs. - Under tow and positioning rig.

APRIL 22, 1971

11 Hrs. - Rigging up. 10 Hrs. - Run and drive 30'' - 1'' wall conductor to 355 ' RKB, 25' penetration, conductor refused. 3 Hrs. - Rigging up to drill.

Water depth 224'. RKB to Mud Line 330'. RKB to mean low wave 106. Air Gap 55' Leg penetration :/'

Final DECCA Coordinates:

57° 20' 37.116'' N 02° 51' 21.426'' E

APRIL 23, 1971

T.D. 735' Progress 735' D.S.S. 1

8<sup>1</sup>/<sub>2</sub> Hrs. - Rigging up to drill out, pick up E.H.A. 5<sup>1</sup>/<sub>3</sub> Hrs. - Drilling to 433' <sup>1</sup>/<sub>2</sub> Hrs. - TOTCO 427' - 1 2 Hrs. - Trip for drill collars 7<sup>1</sup>/<sub>2</sub> Hrs. - Drilling

#### APRIL 24, 1971

T.D. 1495' Progress 760' D.S.S. 2

22 Hrs. - Drilling 2 Hrs. - Clean out flow line.

APRII 25, 1971

T.D. 1502' Progress 7' D.S.S. 3 1 Hr. - Drill to 1502' 1 Hr. - TOTCO 1502' - 2 172 Hrs. - Condition Hole, two trips. 5 Hrs. - Running 20'' casing.

Conoco-Pelican-Gulf 7/9/1 Summary of Drilling Operations cont ... 1 APRIL 26, 1971 Progress 0' T.D. 1502' D.S.S. 4 72 Hrs. - Ran 20 Joints 94 Pound 8 rd 20'' casing. Casing stuck at 793'. Hrs. - Cemented with 800 sacks 12% gel and 300 sacks 2 class B cement. Cement returns to surface. 145 Hrs. - W.O.C. Nippling up 20'' Hydril washed out 30'' - 20'' Annulus to 340' with 2 - 1'' lines. APRIL 27, 1971 Progress 833' D.S.S. 5 T.D. 2335' Hrs. - Nipple up, test 20'' casing and 20'' Hydril 9 to 500 p.s.i. ok. 32 Hrs. - Go in hole, drill cement 764' - 793', clean 26'' hole to 1502'. 91 Hrs. - Drilling with Bit No 2. 2 Hrs. - Clean out flow line. APRIL 28, 1971 Progress 685' D.S.S. 6 T.D. 3020 Hr. - TOTOO 2489' - 10 3 Hrs. - Short tria. 15 Hrs. - Deill to 2489' Hrs. - Short trip to clean hole. Hrs. - Drilling to 3020'. Hrs. -. Short trip and clean flow line. 10 APRIL 29, 1971 T.D. 3531 Progress 511! D.S.S. 7 Hrs. - Drill to 3531' 15 42 Hrs. - Circulate short trip, some drag. Hr. - Circulate, condition hole. Hr. - TOTCO 3531' - 1. 1 Hrs. - Measure out of hole, no correction. 3 APRIL 30, 1971 T.D. 3531 D.S.S. 8 Progress 0 Hr. - Attempt to log, stopped 1471'. 1. Hrs. - Trip to condition hele, bridge at 1471'. 6 - Attempt to log, stopped 1471'. ] Hr. Hrs. - Trip to condition hole, increase mud weight 8 to 12.0 pound/gal. Bridges at 1471' and 2900'. Hrs. - Running 13-3/8'' easing.

Consco-Peliban-Gulf 7/9/1

Summary of Drilling Operations cont ...

<ul> <li>MAY 1, 1971</li> <li>T.D. 3531 Progress 0 D.S.S. 9</li> <li>7 Hrs Finish running 13-3/8" casing. Ran 92 joints 13-3/2" K-55 casing set at 3511", float collar at 3436, mul line hanger at 341". Generated with 1800 sacks class B with 125, gel and 300 sacks class "B" neat. Generat returns to surface. Bumped plug with 1500 p.s.i. float held. Job complete 13.65 pm 30 April 1971.</li> <li>17 Hrs W.O.C. releazed 13-3/6" riser. Washed cement out of 201" - 15-3/8" semulus. Could not reconnect riser. Pulled and layed down riser. Removed 201" hydril. Reman riser with centralizer. Could not connect.</li> <li>MAY 2, 1971</li> <li>T.D. 3551 Progress 0 D.S.S. 10</li> <li>10 Hrs Pulled riser, dressed threads on running tool. Ran and welded riser, screwed in 5 turns, would not hold pressure.</li> <li>10 Hrs Pulled riser, dressed threads on prunning tool. Ran and welded riser, screwed in 5 turns, would not hold pressure.</li> <li>10 Hrs Pulled riser, Notified running tool by removing lower threads with grinder. Replaced 0-ring and pocking. Roren riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730 Progress 199' D.S.S. 11</li> <li>2 Hrs Flock X-bushing. Test bushing and casing 1500 p.s.i. 250 p.s.i on Addition to 2000 p.s.i. 2500 p.s.i. on Addition of the sembly. Go in hole.</li> <li>4 Hrs Pick up bottom hole assembly. Go in hole.</li> <li>4 Hrs Ditilling.</li> </ul>			
<ul> <li>7 Hrs Finish running 13-5/8'' casing. Ran 92 joints 13-5/2'' K-55 casing set at 3511', float collar at 3435, mud line hanger at 341'. Genented with 1800 sacks class B with 125, 291 and 300 sacks class "B" neat. Genent returns to surface. Bumped plug with 1500 p.s.i. float held. Job complete 13.45 pm 30 April 1971.</li> <li>17 Hrs W.O.C. releazed 13-5/8'' riser. Wached cement out of 20'' - 13-3/8'' emulus. Could not re- connect riser. Pulled and layed down riser. Removed 20'' hydril. Reran riser with centra- lizer. Could not connect.</li> <li>MAY 2, 1971</li> <li>T.D. 3531' Progress 0 D.S.S. 10</li> <li>10 Hrs Pulled riser, dressed threads on running tool. Ran and welded riser, screwed in 5 turns, would not hold pressure.</li> <li>10 Hrs Priled riser. Modified running tool by re- moving lower threads with grinder. Replaced G-ring and packing. Reran riser connected, teated with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730' Progress 199' D.S.S. 11</li> <li>‡ Hr Pack 4-bushing. Test bushing and casing 1500 p.s.i. o.k.</li> <li>5½ Hrs Mipple up B.O.P.</li> <li>5 Hrs Freit 0.0.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k.</li> <li>4½ Hrs Pick up bottom hole assembly. Go in hole.</li> <li>4½ Hrs Drill Flug and float collar at 3431', shoe at 3511'.</li> </ul>	MAY 1, 1971		
<ul> <li>13-5/21' K-55 casing set at 2511', float collar at 3436, mud line hanger at 341'. Gemented with 1800 sacks class B with 125, gel and 300 sacks class "B" neat. Gement returns to surface. Bunped plug with 1500 p.s.i. float held. Job complete 13.45 pm 30 April 1971.</li> <li>17 Hrs W.O.C. releaced 13-5/6' riser. Washed cement out of 20'' - 15-5/8'' ennulus. Could not reconnect riser. Pulled and Layed down riser. Removed 20'' hydril. Reran riser with centralizer. Could not connect.</li> <li>MAY 2, 1971</li> <li>T.D. 3531' Progress 0 D.S.S. 10</li> <li>10 Hrs Pulled riser, dressed threads on running tool. Ran and welded riser, screwed in 3 turns, would not hold pressure.</li> <li>10 Hrs Pulled riser. Modified running tool by removing lower threads with grinder. Replaced 6-ring and packing. Reran riser connected, tetted with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730' Progress 199' D.S.S. 11</li> <li>Mr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k.</li> <li>4 Hrs Nipple up B.O.P.</li> <li>3 Hrs Fick up bottom hole assembly. Go in hole.</li> <li>4 Hrs Pick up bottom hole assembly. Go in hole.</li> <li>4 Hrs Diritl Plug and float collar at 3431', shoe at 3511'.</li> </ul>	T.D. 3531	Progress 0 D.S.S. 9	
<ul> <li>Bunped plug with 1500 p.s.i. float held. Job complete 13.45 pm 30 April 1971.</li> <li>17 Hrs W.O.C. releaced 13-7/8'' riser. Wached cement out of 20'' - 13-5/8'' enclus. Could not reconnect riser. Pulled and layed down riser. Removed 20'' hydril. Reran riser with centralizer. Could not connect.</li> <li>MAY 2, 1971</li> <li>T.D. 3531' Progress 0 D.S.S. 10</li> <li>10 Hrs Pulled riser, dressed threads on running tool. Ran and welded rizer, screwed in 5 turns, would not hold pressure.</li> <li>10 Hrs Pulled riser. Modified running tool by removing lower threads with grinder. Replaced 0-ring and packing. Reran riser connected, terted with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730' Progress 199' D.S.S. 11</li> <li>thr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k. 5thrs Nipple up B.O.P.</li> <li>J Hrs Fick up bottom hole assembly. Go in hole. 4thrs Pick up bottom hole assembly. Go in hole. 4thrs Pick up bottom hole assembly. Go in hole.</li> </ul>	7 Hrs	13-5/2'' K-55 casing set at 3511', float collar at 3436, mud line hanger at 341'. Cemented with 1800 sacks class B with 125 gel and 300 sacks	
<ul> <li>T.D. 3531<sup>1</sup> Progress 0 D.S.S. 10</li> <li>10 Hrs Pulled riser, dressed threads on running tool. Ran and welded riser, screwed in 3 turns, would not hold pressure.</li> <li>10 Hrs Prlled riser. Modified running tool by re- moving lower threads with grinder. Replaced O-ring and packing. Reran riser, connected, tested with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730<sup>1</sup> Progress 199<sup>4</sup> D.S.S. 11</li> <li>‡ Hr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k.</li> <li>5½ Hrs Nipple up B.O.P.</li> <li>3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k.</li> <li>4½ Hrs Pick up bottom hole assembly. Go in hole.</li> <li>4½ Hrs Drill Plug and float collar at 3431<sup>1</sup>, shoe at 3511<sup>6</sup>.</li> </ul>	17 Hrs	Bumped plug with 1500 p.s.i. float held. Job complete 13.45 pm 30 April 1971. W.O.C. releaced 133/8'' riser. Washed cement out of 20'' - 13-3/8'' annulus. Could not re- connect riser. Pulled and layed down riser. Removed 20'' hydril. Reran riser with centra-	5
<ul> <li>10 Hrs Pulled riser, dressed threads on running tool. Ran and welded riser, screwed in 3 turns, would not hold pressure.</li> <li>10 Hrs Polled riser. Modified running tool by re- moving lower threads with grinder. Replaced O-ring and packing. Reran riser, connected, tested with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730' Progress 199' D.S.S. 11 <ul> <li>Image: Hrs Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k.</li> <li>Hrs Nipple up B.O.P.</li> <li>Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k.</li> <li>Hrs Pick up bottom hole assembly. Go in hole.</li> <li>Hrs Drill Plug and float collar at 3431', shoe at 3511'.</li> </ul> </li> </ul>	MAY 2, 1971		
<ul> <li>Ran and welded riser, screwed in 3 turns, would not hold pressure.</li> <li>10 Hrs Prlled riser. Modified running tool by removing lower threads with grinder. Replaced O-ring and packing. Reran riser, connected, tested with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>MAY 3, 1971</li> <li>T.D. 3730<sup>4</sup> Progress 199<sup>4</sup> D.S.S. 11 <ul> <li># Hr Pack &amp;-bushing. Test bushing and casing 1500 p.s.i. o.k.</li> <li>5<sup>1</sup>/<sub>2</sub> Hrs Nipple up B.O.P.</li> <li>3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k.</li> <li>4<sup>1</sup>/<sub>2</sub> Hrs Pick up bottom hole assembly. Go in hole.</li> <li>4<sup>1</sup>/<sub>2</sub> Hrs Drill Plug and float collar at 3431<sup>4</sup>, shoe at 3511<sup>6</sup>.</li> </ul> </li> </ul>	T.D. 3531	Progress 0 D.S.S. 10	
<ul> <li>10 Hrs Pelled riser. Modified running tool by removing lower threads with grinder. Replaced O-ring and packing. Reran riser, connected, tested with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was first removed.</li> <li>4 Hrs Cut off casing. Nippling up.</li> <li>14Y 3, 1971</li> <li>T.D. 3730' Progress 199' D.S.S. 11 <ul> <li>Hr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k.</li> <li>5½ Hrs Nipple up B.O.P.</li> <li>Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k.</li> <li>4½ Hrs Pick up bottom hole assembly. Go in hole.</li> <li>4½ Hrs Drill Plug and float collar at 3431', shoe at 3511'.</li> </ul> </li> </ul>	10 Hrs	Ran and welded riser, screwed in 3 turns,	
4 Hrs Cut off casing. Nippling up. IAY 3, 1971 T.D. 3730 <sup>4</sup> Progress 199 <sup>4</sup> D.S.S. 11 <sup>1</sup> / <sub>2</sub> Hr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k. 5 <sup>1</sup> / <sub>2</sub> Hrs Nipple up B.O.P. 3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k. 4 <sup>1</sup> / <sub>2</sub> Hrs Pick up bottom hole assembly. Go in hole. 4 <sup>1</sup> / <sub>2</sub> Hrs Drill Plug and float collar at 3431 <sup>4</sup> , shoe at 3511 <sup>4</sup> .	10 Hrs	Pelled riser. Modified running tool by re- moving lower threads with grinder. Replaced O-ring and packing. Reran riser, connected, tested with 1000 p.s.i. o.k. Apparently third thread in hanger was damaged when riser was	)
T.D. 3730 <sup>4</sup> Progress 199 <sup>6</sup> D.S.S. 11 <sup>1</sup> / <sub>2</sub> Hr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k. 5 <sup>1</sup> / <sub>2</sub> Hrs Nipple up B.O.P. 3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k. 4 <sup>1</sup> / <sub>2</sub> Hrs Pick up bottom hole assembly. Go in hole. 4 <sup>1</sup> / <sub>2</sub> Hrs Drill Plug and float collar at 3431 <sup>4</sup> , shoe at 3511 <sup>4</sup> .	4 Hrs		
<sup>1</sup> / <sub>1</sub> Hr Pack K-bushing. Test bushing and casing 1500 p.s.i. o.k. 5 <sup>1</sup> / <sub>2</sub> Hrs Nipple up B.O.P. 3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k. 4 <sup>1</sup> / <sub>2</sub> Hrs Pick up bottom hole assembly. Go in hole. 4 <sup>1</sup> / <sub>2</sub> Hrs Drill Plug and float collar at 3431', shoe at 3511'.	MAY 3, 1971	•	
p.s.i. o.k. 5 <sup>1</sup> / <sub>2</sub> Hrs Nipple up B.O.P. 3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k. 4 <sup>1</sup> / <sub>2</sub> Hrs Pick up bottom hole assembly. Go in hole. 4 <sup>1</sup> / <sub>2</sub> Hrs Drill Plug and float collar at 3431', shoe at 3511'.	T.D. 3730 <sup>4</sup>	Progress 199' D.S.S. 11	
5½ Hrs Nipple up B.O.P. 3 Hrs Test B.O.P., choke and kill lines to 5000 p.s.i. 2500 p.s.i on hydril o.k. 4½ Hrs Pick up bottom hole assembly. Go in hole. 4½ Hrs Drill Plug and float collar at 3431', shoe at 3511'.	1 IIr		
4 <sup>1</sup> / <sub>2</sub> Hrs Pick up bottom hole assembly. Go in hole. 4 <sup>1</sup> / <sub>2</sub> Hrs Drill Plug and float collar at 3431', shoe at 3511 <sup>°</sup> .		Nipple up B.O.P. Test B.O.P., choke and kill lines to 5000 p.s.i.	1
		Pick up bottom hole assembly. Go in hole. / Drill Plug and float collar at 3431', shoe at	
	6 Hrs		

14

rage.

# CONOCO NORWAY INC P.O.Box 130 4056 Tananger, Norway

# 18th May 1971

# SUMMARY OF DRILLING OPERATIONS CONCCO-PELICAN-GULF 7/9-1

0800 Hours May 4th - 0800 Hours May 18th 1971 Reports as of 0800 am for day reported covering previous 24 hours.

MAY 4, 1971

T.D. 5128' Progress 1393' D.S.S. 12
ll Hrs. - Drilling
l Hr. - Short trip - 40,000 overpull first 5 stands
1/2 Hr. - Drilling
1/2 Hr. - Circulate
11 Hrs. - Drilling

MAY 5, 1971

T.D. 5880' Progress 752' D.S.S. 13 1 Hr. - Finish short trip 2-1/2 Hrs. - Drilling to 6244' 2 Hrs. - Circulate and totco 5-1/2 Hrs. - Trip for bit no. 4 13 Hrs. - Drilling

MAY 6, 1971.

T.D. 6369' Progress 489' D.S.S. 14

 8
 Hrs. - Drilling to 6118'

 1/2
 Hr. - Circulate and survey

 7
 Hrs. - Trip for bit no. 5. Pick up 3 additional DC and rearranged stablizers. Ran in hole. No drag and no fill

 8-1/2
 Hrs. - Drilling 12-1/4 hole.

MAY 7, 1971

T.D.	70581	Progress	6891	D.S.S.	15	
8 9		- Drilling t - Circulate,		trin for	hit no	6
2 7		no drag, n Drilling t	o fill.	arth rot		0

Cont....2...

· ·	Coo-	-huittem-d	dit iver			
			ing Operations con			
	<u></u>			· ·		16
_	MAV O	1071	•			1 U
0	MAY 8,	1971				· 
	T.	D. 7058'	Progress O	D.S.S. 16		
	. 1	1-1/2 Hrs.	- Condition hole,	short trip, 15'	fill	
	· 1 	-1/2 Hrs.	- Condition hole - Full out to log			
· · · ·			- Ran Schlumberge:	r gama-ray soni	c and IES logs.	ろ
· . <del>.</del>		l Hrra	Schlumberger T.I - Lay down 9-1/2 a	D, 70611	oollars Run	$\mathcal{O}$
			in hole		oolaalist nun	
*	•	1/2 Hr.	- Condition hole.	•. • •		
	<u>MAY 9,</u>	<u> 1971</u>		•		
•	T.	D. 7058'	Progress Ø	D.S.S. 17	•	
				¢		
	2	1/2 Hr. 2-1/2 Hrs.	- Condition hole - Pull out of hole	Э		
	2	2-1/2 Hrs.	- Set Cameron mud	line hanger	to a state of the second second	
<b>.</b>	- 11	Ars.	- Ran 172 joints of casing set at 70	)-5/8" - 4/ 105 )34' landed in si	uttress 16 sea hanger	A Li II
		IIma	at 345' RKB.	· · · ·		Ĭ Ÿ İ
·	. 4	- nrs.	- Circulated casir sacks 4% Gel and	lg and cemented i l 800 sacks neat	class "B"	1
		•	retarded cement. to surface.	Approximately '	75 sacks return	
	1	-1/2 Hrs.	- Removed riser, w	ashed out climen	t, reconnected	
	2	Hro	<ul> <li>tested to 1500 p</li> <li>Rig down Hallibu</li> </ul>		n while W O C	
. •	<u>د</u>		- Mig down narriot	aroon - arppic a		
	<u>MAY 10,</u>	1971	• *			
	Т.	D. 7090'	Progress 32'	D.S.S. 18		
	10	-1/2 Hrs.	- Nipple up	· · · · · · · · · · · · · · · · · · ·	•	
			- Test BOP, choke			ſ
	1	-1/2 Hrs.	Hydril and casin - Pick up BHA	rg (0 2000.58T* (	015.0	ľ
	. 4	-1/2 Hrs.	- Go in ĥole, inst	all casing prote	ectors on	"
•	. 3		every joint. - Drill plug and f	loat collar at (	5941'	
	1	-1/2 Hrs.	- Drill cement to	7020', tested ca	sing to 2500	•
	••	1/2 Hrs.	psi. ok, drill s - Drilling	noe av 1055.	•	•
	MAY 11,	1071			· -	
~	Τ.	D. 7273'	Progress 1831	D.S.S. 19		-
0	6		- Drilling 7090' t		. •	
۽ الاختيا	· 1		- Circulate for sa - Trip out, pick u		to in hole.	[
		• •	circulate, drop	bell.		`{
	. 4		- Cutting core no. barrel apparentl		24 feet,	
	2	Hrs.	- Pulling out of h			

•

• --

·

r.

Conoco-Pelican-Gulf 7/9-1 Summary of Drilling Operations cont....

 $\mathbf{O}$ 

	<u>, MAY</u>	12, 1971		•	· · · · ·
		T.D. 7415	Progress 142'	D.S.S. 20	· .
		1-1/2 Hr 3 Hrs 3 Ers	Pull out with co Necover core no feet, rec. 15-1, Go in hole with Drilling	1 - 7249 - 7273 /2 fect. bit no. 8	• • • • •
•		1-1/2 Hr	<ul> <li>Condition mud, a mud weight to 14</li> <li>Drilling to 740</li> <li>Circulate, Toted</li> <li>Trip for Core No</li> <li>Circulate, drop</li> <li>Cutting Core No.</li> </ul>	1.0 lb/gal.	~
	MAY	13, 1971			
		T.D. 7650'	Progress 235'	D.S.S. 21	
• .	•	1 Hr 2-1/2 Hrs 2 Hrs	• Cutting core No. • Pull out of hold • Lay down core No 10 feet	2 to 7416'. Ba: 5. 2 7403 - 7416	rrêl jammed. ' - Recovered
		3 Hrs 1/2 Hr	• Glip and cut dri • Go in hole. • Wash and noam 29 • Drilling to 7650	5' to bottom	
	MAY	14, 1971			j)
		T.D. 7891'	Progress 241'	D.S.S. 22	. /
		15-1/2 Hrs	• Trip for bit No. • Drilling to 789 • Totco and trip :	11	
	MAY	18, 1971			• •
		T.D. 9281	Progress 1390'	D.S.S. 26	
	• •	10-1/2 Hrs 1 Hr 3-1/2 Hrs 1/2 Hrs 2-1/2 Hrs 3 Hrs	- Girculate C - Drilling		A second s
- •		1 Hr 3-1/2 Hrs 3 Hrs 2-1/2 Hrs 1 Hr 1. Hr	· Rull out of hold	2.	
			3		Cont4.

ł,

de co-icanoan-Guat a 2-1

Summary of Drilling Operations "cont....

# MAY 18, 1971 cont..

				Drilling					
	1/2	Hr.		Survey					
	6	Hrs.	·	Trip				• • •	•
	3-1/2	Hrs.	-	Drilling	,				
	1	Hr.	• •	Circulate	Э			- 4	
	7	Hrs.		Drilling					
•	2	Hrs.	-	Drilling					
	6	Hrs.	•••	Trip for	bit				
	6-1/2	Hrs.	**	Drilling		•			
	7-1/2	Hrs.	<b></b>	Trip for	bit,	BHA,	cut	drill line	
•	2	Hrs.	<b>.</b>	Drilling		-			

# CONOCO HORWAY INC.

P.O.Bóx 430 4056 Tananger Norway

# 26th Eay 1971

#### SUBLARY OF DRILLING OPERATIONS

#### CONOCO-PEDICAN-CULE

0800 Hours May 19th - 0800 Hours May 26th 1971 Reports as of 0800 am for day reported covering previous 24 hours.

MAY 19, 1971

T.D.	94871	Progress	2061	•	D.S.S.	27
	2401	71061000	L.00		1.10.000	

24 Hrs. - Drilling

MAY 20, 1971

T.D. 9614' Progress 127! D.S.S. 28 4 Hrs. - Drilling 1-1/2 Hrs. - Short trip 4-1/2 Hrs. - Drilling 5 Hrs. - Frip for bit 3 Hrs. - Frilling 1 Hr. - Circulate 1/2 Hr. -- Drilling 1 Hrs. - Circulate 3-1/2 Hrs. - Pull out of Hole to log

MAY 21, 1971

T.D. 9614' Progress 0 D.S.S. 29

24 Hrs. - Rig up and run IES, FDC, SSL, MLL, Sonic - GR, HRD, Now shooting SWC

### MAY 22, 1971

T.D.	9614*	Progress 0 D.S.S. 30
3-1/2	Hro.	<ul> <li>Sidewell coring. Recovered 74 of 90 shots.</li> <li>Ley down drill collars</li> <li>Go in hole, spot plug No. 1 7140' - 7300' with 75 sacks class E coment</li> </ul>
		<ul> <li>W.O.C Check top cement 7140'</li> <li>Set retainer in 9-5/8'' casing at 6900'. Broke down formation below retainer at 1000 p.s.i., mud weight 14.0 lb/per gal. Uquessed 150 socks elass "E" below retainer, spotted 50 sacks on top retainer.</li> </ul>

19

Cont......

Conoco-Pelican Gulf 7/9-1	Радо 2
Summery of Drilling Operations	cont 20
MAY 23, 1971	
T.D. 9614' Progress 0	D.S.S. 31
	ner, would not hold pressure
4 Hrs Full out of tool. Go in	hole. Repoved damaged cementing hole. Spotted 200 sacks coment tainer. Tested 1500 p.s.i. ok.
11 Hrs." - Laying down	drill pipe, nipple down BOP s class B at 468', washed out at
5 Hrs Could not re	move 9-5/8" riser. Made two cuts. 45'. Could not pull.
MAY 24, 1971	
T.D. 9614' Progress O	D.S.S. 32
19 Hrs Jarred 9-5/8" layed down. 09 Cut 30" at 33	at 20" at 339'. Layed down.
	ather to pull 30" riser
HAY 25, 1971	
T.D. P & A	D.S.S. 33
<ul> <li>Hrs Waiting on we</li> <li>Hrs Pull and ley</li> <li>Hrs Preparing to</li> </ul>	down 30" conductor
MAY 26, 1971	
	D.S.S. 34
24 hrs: Hrs Waiting on we	ather .
MAY 27, 1971	
	D.S.S. 35
24 . Hrs Waiting on M	$\mu$ eathor $\mu$
MAY 28, 1971	
24 Hrs Waiting on w	D.S.S. 36
MAY 29, 1971	
T.D. P and A	D.S.S. 37
÷	
2 Hrc Jacking down tow for 8/12-	- Hooking up tugs - Under 1 1000 hours May 29 1971. for rig and well. Plugged
· · ·	

•

 $\mathbf{O}$ 


 $\bigcirc$ 

TR.

\*\*\***\*\*\***---

ورائة للترويك بالغرام تكرده

- - F



21 APRIL - 29 MAY 1971

RUN 133/8 CSG

RUN 95/8 CSG.

LOG, POA, WOW

2

3

4

5

6

7

8

9

10

ERT

X

# CONOCO NORWAY INC.

 $\langle \rangle$ 

# CONOCO-PELICAN-GULF 7/9-1

Drilling Time Analysis

	-			0	
	. *	Hours	Days	0/0	,
	MOVING	18-1/2	0.8	2.1	
	RIG UP - DOWN	17	0.7	1.8	
	CONDUCTOR	10	0.4	- 1.0	
	DRILLING	301	12.5	32.2	
ļ	TRIPS - DRILLING	106	4.4	11.3	
-	REAM	1/2		-	•
	CORING	30	1.2	3.1	
	CASING AND CEMENT	47	2.0	5.2	
	W.O.C NIPPLE UP	101	4 - 2	10.9	
	CONDITION HOLE	65	2.7	7.0	
	TOTCO	4	. 0.2	0.5	
	CIRC. SAMPLES	5	0.2	0.5	
	LOGGING	52 <sup>~</sup>	2.2	5.7	
D	P. AND A.	59-1/2	2.5	6.4	
	WOW TO MOVE	114	4.8	12,.3	
		930-1/2	38.8	100.0	

. La			Ó									' ŗ		strich /			<b>!</b>						· ·	•		(	2	• •
1	· - · · · ·			(»	 F	<del>.</del>			· [			·.	.'⊈⊈ 	103 C.J.	ii *	J S.N	LESMAN	l1			•		ĥ					Page
;	CONT	6 A C T C P	· · · ·	· · · · · · · · · · · · · · · · · · ·			j	<i>'</i> .		1AKE													•		,			
					FICLD					1ZE			COLLARS	: OD X	D X U		X					MO.	/ t	DAY Si J	/ ··	YR.	T.P. D	RILLERS
1			-	,					ļ	NO. 1_	- 11						X Y		SPUD UNDER	SUPEA	<u>.</u>		/ {/.		/ , ` ,		· ·	na an a
	STATE								1				DAILL PI	PE	$\langle 1 \rangle /$				UNDER				: /	• .				R SOURCE
1	- SEC./	/RANG							*				TOOL 10			1	<u> </u>		TOTAL				/	. :	/			SOURCE
.1	en me EUN	SIZE	A MAKE		SEPISI	1513	3 - <b>3</b> 2ne					FEET	CUA.	W7.	·	21112	1											
	1997 1997 1997			TYPE	SERIAL NO	1	3 - 32ne R or 2	3	טז	, EET	HOURS	PER -HOUR	CUA. HOURS	1000 L8S.	13.2.M.	PUVP PRESS,	FUMP Liner	SPM	Liper	\$2/λ	VI. N	PRO:	70ames 7. <u>19.7.1</u> 9.	0ev 7	1 1 1 1 1 1	Com	3.1/4 V/	1 
1	- <u> </u>	~ <u>,</u>		<u> `</u>		÷		/	502	1132	_36		36	<u>·; .</u>	1.11				• •			• •		11	. 		•••	1
5			· · ·		• • • • • • • • • • • • • • • • • • •	<b>.</b>	. 	3	<u>531</u>	<u>26 25</u>			71	<u>,                                    </u>		1					, , , . 	·   ·	 	7				
	· ·		•			· ·	<u></u>	5	294	<u></u>	31	<u>, ; ; ;</u>	102		·							<u>.   _</u>		_ . 	<u>                                     </u>	<u></u>	ļ., ï.	
1		<u> </u>	ļ. 			$I_{2}$	·		1 ] 8	<u>. 7 -</u>	21	42	123	1.11	1.7	T			· .		•		·  ·  -	<u> </u>	<u>  :</u>	1	Ï	
•:	·			<u>//</u>			<u>. :                                    </u>						137	· · · ·	<u></u>	ļ			· · ·	· .		_	·	_ <u> </u>		<u>/-</u>	1	
	. <u>.</u>		· · · · · · · · · · · · · · · · · · ·	1. 24	— <del>— — —</del> — — — — — — — — — — — — — — —		_: <u> </u> :		053		3		146	· · · ·	100		· · ·				•   ; 				;	11	; ; 	¥
		· · · · · · · · · · · · · · · · · · ·		115		<u> </u>	<u>i 1 -</u>		249	191	<u>7'/</u> 2	2	1.54	;	 						: 	<u>i. </u>	· -	_  _ -		.;	<u></u>	
3	·	ļ		· · · · · ·					2.73	· · · · ·	Ч	<u>  /·</u>	158	f	$\frac{p_{f}}{p_{f}}$				/ 			·	··	·	_			
				<u> 2403</u>		1	<u>: ]</u>		403		41/2		1121	2				•								, 		
•	. <u></u>			<u>, (</u>				{	116		24	7	165	<u> </u>	+	1.1.	<u> </u>				·					ļ	 	
			· · ·	<u> </u>			<u>i                                    </u>	7	650		147	2/2:	179%	/ . <i></i>	<u>  ' /</u>	+	1			•		://	·		.	ļ	ļ	
-			· · · · ·	<u>i  </u>		14	4	1 78	<u>891</u>	311	<u>i 54</u>	1/:	195		<u>. 117.</u>	ļ	ļ]		· 7						;	. ,	<u> </u>	
4 4 4	;		·			$P_1^*$	///	18	285		14	13	209		1	ļ					::, .	•	·		<u>                                     </u>	7	7	
	·	<u></u> .	··• }``			:4		4	v	1 1		<u>, ,</u>	2211	2	1.56			•			-	-			3		7	
•			·			54	··	14 8	933	.; )	1/	1	232/			ļ					••	·   .	2	<u> </u>		10	Ĩ	
			· · · ·			<u>;;</u>		9	226	1,1	12/2		2.45 251	<u> </u>	;: <del>-</del> `	 						·			1	<u> </u>	<u>. 7</u>	
			. 	-17 i i i		14	<u>  7  </u>	<u> </u>	268		<u> </u>		251				, ,			·	<u>.</u> .	·			<u> ``</u>	1	17	
1	·		1					G	552		34		286		1				•	- <b></b>	·  -		╺┼╾╴┞╴		<u> `-</u>		<u> </u>	
	-	•. •		· · · · ·	····~		<u>     </u>	9	614	<u></u>	31/2	<u>, 11</u>	287	h	1.0	<u>.</u>						·  • 		_	ļ			
		·													.					Ì						<b> </b>		
ł			1										;				1		į					ļ		1		2

. . . . . . . . .

-----

-- --**..**... · - - -

......

i - ---


----

••••• .....

		Ľ	5-0m 6" 4+**	$\sim$	1				•				C 1.1 1	<b>.</b>				Į			4					
										,	WELL	DATA	3 m				•									
												••			•	•									PAGE	3
AG-545-A	UCLCC TT IS							SURVEY T P. CASIN					ASING SIZE	DEP	77H	DRLG.	DAYS			BIT	r size		<u> </u>			
UF 612710	<u> UCA, C</u>	<u>/</u>	<u>EL </u>	$\partial \partial A$	<u> </u>	<u> Gi i</u>	<u> ترينه</u>	S	EC.		1	r	F.													<u> </u>
WELL	914-1							F	ELD					•												
CONTRAC	TOR	<u></u>						C	OUNTY					_	1	NTERMEDIAT	E									
ENGINEE	<u> </u>	<u> </u>		-		<u> </u>			TATE			COUNTR	Y		P	RODUCTION								<u></u>		
	·	•	·					<u> </u>								·····					I		T			1
			VISCO	OSITY	.		GE	LS	рH	FLUI	D LOSS	, CL B.	A	KALINI	<u>۲۲</u>			ļ	RETORT		ACT	YITY	RA	710	# Sbi	
				[	-	RR. 5°F			веск		1 500 PSI			•				96	%	%		ļ				
1,71			İ		!,	1	ļ		STRIP	AP!	300 °F					CA	Mg	OIL	SOL	WATER	As	Am	OIL	H2O	CEC	
DATE	DEPTH	WT.	SEC.	CPS.	PV	YP	0	10				100012	PF	PiA	M	F ppm	חלפק	1			1	<u> </u>			<u></u>	╞
<u> </u>		2000 2000 2000	22		-}'				11.17	+		<u> </u>	+						· ·	•	<u> </u>	<u> </u>		$\left[ - \right]$		+-
		9.1 5.3	131				{		10.0			1 		<u> </u>	_ <u></u>			<u> </u>	 	+		-				+
 ; *;	12.56	14							, (	1			<u>†</u>					+			·					1 *
<u></u> 54.	1.					┟╌╍╴									•					1	1					
17	,				177	1	$\langle \cdot \rangle$	12	1 .:	1:	·	11 :00 -	1/:-			2.5		<u> </u>	14	20	! 		<u> </u>			
. •	1.1.1	· · · · +	<u> </u>			<u> </u>	C	,*	11 7									<u> </u>	14	175	 	<u> </u>	<u>  </u>			-
			130		12		2	12	11.	1			1.1	┉┈╴╴╴┥		- 1.			<u> </u>				+	1		
<u> </u>	<u>i - i</u>		<u> </u>	<u> </u>	11			12	11			12.5	15			- * ?	}						<u>+</u>	1		+
11.1	/	11 1	<u>  51</u>   73		17	÷	2	172 10	11.5			12.5	10					Ġ	12.	\$2	1					- <b>†-</b>
	<u>+ 1</u>	12.5	57		17	<u> </u>	5	127				177	1.7			1050	· ·	(	1.7	75		1	1			
<u></u> 		1.7.7		1	107	$\frac{1}{1}$	5	1	177			14	1.5			1-12		(-	2.2	18	1					T
·	· 1. * .	130	53		23		6		11.2		2	10	19.0	3	· · ·	,		Ś	17 7	72-	<u> </u>		<u> </u>	<u> </u>		1
	1	1.5.2	Ni.		1:2.5		2.	6	11.3	1-	=	24	1.3				ļ	5	22	171			<u> </u>	ļ		
1	70 :	132	57		24	12	4	10	11.5			14	1.7	<u>;</u> ;	<u> </u>	3	<u> </u>	5	24	73	1			+		
		1.1	55					1	·			14	1/5			·			27	72-		1	- <u> </u>	+	<u> </u>	┽
1	<u> </u>	131	<u>  67</u>   53					12					1.4		}		+					+	1	+		╉
<u></u>		133				· ` ``;			- j			13		<u> </u>		17		1.		1. 1	1		1	1		Ť
,,, , , , , , , , , , , , , , , , , , ,	12	11.2					2.					/ 3	1.2	 ].~.>	į	ア	1	16.5		1.5	•	1,		1		
<u> </u>	7	174.0			+			114		7		12	1. :	>	1.	7,			175	175.5						T
1. 1.1		11.0										14	1. 2	17 -		<u> </u>		1.0							<u> </u>	_
									T		<u></u>	, Y	1/2	12.	,1 ,1	1 -	<u> </u>	<u></u>		1:17				<u> </u>	<u> </u>	4
·		1				1.,							1 4		1	<u> </u>	<u> </u>	1 3			_ <u> </u>				<u>+</u>	
1		1. 5				·   ·		11					. <u>  /</u>		<u> </u>			4-4-5								7 4
		1.5 3		:				<u>6.н</u>	h		·	<u>ן אין אין אין אין אין אין אין אין אין אי</u>			1	<u> </u>	┛,────	1	<u> </u>		OST:					


ς,

...



Ô





PAGE ] MAG-5 45-A BIT SIZE DRLG. DAYS CASING SIZE DEPTH OPERATOR SURVEY SEC. Conco- Pruses - Curt R . T FIELD SURFACE WELL 7 INTERMEDIATE COUNTY CONTRACTOR COUNTRY PRODUCTION STATE ENGINGER # вы RETORT ACTIVITY RATIO ALKAUNITY FLUID LOSS VISCOSITY GELS pН CL ΕI % % CORR. 115°F BECK 1 100 PSI 50C SI % CACL 📋 301 °F APT CEC Am OIL H20 STRIP NACL 🗖 As Mg ĊA WATER HT-HP OIL SOL PF РM MF ppm ppni 0 10 PV YP SEC. CPS. DATE DEPTH WT. 14 6-5 2 1-211.4 21 12 .7 1.15 1.00 15 Ę 141 11 11.0 11.1 1.5 24 2 C:C100 (.-11-13 .45 10 1.10 ÷...۲ 11 . 1.4 1-40 -, 31 , . , **n** ... 4.ª 2. 1 ---. . . - • . . . , ÷ • 5 7 ×. 3 COST: COMPLETION FLUID TYPE: DATE SPUD: DATE T.D.: Б.H.T. 57 COST: PACKER MUD TYPE: 100.00