


NAME	VALUE	UNIT
DSEC	4.50000	MHMD
BHS OPEN	0.0	F
DD	0.0	
NAME	VALUE	UNIT
BS	0.0	IN
SBR	1.00000	DHMM

SENSOR MEASURE POINT TO TENSION REFERENCE POINT	
SFL	1.2 METER
SPAR	-.2 METER
TENS	.0 METER
ILD	1.3 METER
SR	-.2 METER



SENSOR MEASURE POINT TO TENSION REFERENCE POINT	
SFL	1.2 METER
SPAR	-.2 METER
TENS	.0 METER
ILD	1.3 METER
SR	-.2 METER

FIGURE 13.  
30/3-1 SP PLAYBACK  
(from page 32)