

# Norsk Hydro a.s

Oslo - Norway



Well no. 16/3-2		Core report			Core no's 1
Interval 1985 - 1998		Area Norwegian North-Sea	Cut 13 m		Date 28 - 2 - 76
Scale 1 : 100		Well R.K.B. 24 m	Recovery 0 m		Geologist Rydberg
Depth scale	Re - covery	Lithological column	Depths	Lithological descriptions	Shows
				No recovery	
Well		Core report			Core no's

# Norsk Hydro a.s

Oslo - Norway



Well no. 16/3-2		Core report				Core no's 2
Interval 1998 - 2006.5 m		Area Norwegian North-Sea		Cut 7.5 m	Date 28-2-76	
Scale 1:100		Well R.K.B. 24 m		Recovery 1.5 m	Geologist Rydberg	
Depth scale	Recovery	Lithological column	Depths	Lithological descriptions	Shows	
1998 1999				<p>Sandstone: crs - v crs loc gvl, ang - subang poor srt semicons, tr pyr, chlorite? sl mic. Grading to sst rnd - subrnd.</p> <p>Recovery 24%</p>	Nil	
Well		Core report				Core no's

# Norsk Hydro a.s

Oslo - Norway



Well no. 16/3-2		Core report				Core no's 3
Interval 2017 - 2019		Area Norwegian North-Sea		Cut 2 m	Date 29-2-76	
Scale 1 : 100		Well R.K.B. 24 m		Recovery 1 m	Geologist Rydberg	
Depth scale	Recovery	Lithological column	Depths	Lithological descriptions	Shows	
2017 2018			+++++ +++++	Granite: pinkish with biotite, muscovite, quartz, and red-orange feldspar medium coarse grained.  Recovery 50 %.	Nil	
Well		Core report				Core no's